

Korea Hydrographic and Oceanographic Agency



351 Haeyang-ro Yeongdo-gu
BUSAN 49111, Rep. of KOREA
Tel. +82-51-400-4331

RECEIVER	SENDER
NAVAREA XI Coordinator Hydrographic and Oceanographic Department of J.C.G, JAPAN	Nautical Chart Division of KHOA, Republic of KOREA E-Mail : ntmkhoa@korea.kr
Fax. No. +81-3-5500-7171	Fax. No. +82-51-400-4349
Page(Including this one) : 1 Sheet	Date : Jul. 21, 2019

Korean Navigational Warning (No.19-188)

The buoy is drifting. Mariners are advised to navigate with caution

☐ East Coast ~ Ulsan ~ Drifting buoy

☐ Specification

- Characteristics: Fl(5)Y20s
- Diameter(4.3m), Height(6.0m), Weight(7tons)

☐ Position(WGS-84) : **35-20-14.6N, 129-24-21.7E** from 34-55-12.7N, 129-07-16.2E

(Jul. 21, 2019 08:30 KST)

☐ Remark: The buoy has moved about 53km NE of the existing location and is drifting at 5~6km/h NE. The light is expected to have been damaged.

☐ Chart affected : No. 2112

☐ Source : KHOA